

State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

July 25, 2001

TO:

Minerals File

FROM:

Tom Munson, Senior Reclamation Specialist

RE:

Site Inspection, Levin Stone Mining Company, Levin Stone #4 Project, S/027/086, Millard

County, Utah

Date of Inspection:

June 19, 2001

Time of Inspection:

11:13 a.m.

Conditions:

Sunny, warm

Participants:

Sheri Wysong, BLM; Tom Munson, DOGM

Purpose of Inspection:

To inspect the site while in the area

It appears that there has been some stone removed from the stone yard. Maybe 1/3 to  $\frac{1}{2}$  of the pallets have been removed, but the remainder are still here. We visited the reclaimed pit and determined that is looked fine from the regrading standpoint, but still needs to be seeded. The BLM holds a bond on this site.

Photos were taken of the site.

jb

cc: Van Falls, Levin Stone

S27-86-ins.doc



P0002236.JPG 06/19/1901



P0002237.JPG 06/19/1901



P0002238.JPG 06/19/1901



P0002239.JPG 06/19/1901



P0002240.JPG 06/19/1901



P0002241.JPG 06/19/1901



P0002242.JPG 06/19/1901



P0002243.JPG 06/19/1901



P0002244.JPG 06/19/1901